



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program January 29, 2013

Reviewed: 

Mine Name: Blind Stream 5-11 Honeycomb	Permit Number: S/013/0004
Operator Name: Floyd Anderson	Inspection Date: September 28, 2010
Inspector(s): L Heppler	Time: 8:00 AM
Other Participants: Dave Herron - USFS	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 12-22-2014 **Bond Amount:** \$25,300 **Permit fee** is up to date

Purpose of Inspection: Routine annual Inspection. This site inspection was last inspected on 09-11-2007.

Inspection Summary: Site had a highwall, 2 working levels, and several waste dumps. Trash was limited, but there was several pieces of equipment on site.

Photos were taken to document site conditions.

Conclusions and Recommendations: Footprint of disturbance appears to be larger than 5 acres. Operator should GPS the site to confirm the disturbed acres. Then the operator has the option to either bond for additional acres or reclaim back to the 5 acres that are bonded. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature 

LAH:eb

cc: Floyd Anderson

USFS- DAHerron@FS.Fed.us

O:\M013-Duchesne\S0130004-Shamrock\inspections\Insp-09282010.doc





Overview of site and access road



Overview of site and access road



Mining horizon



Highwall lower mining level